March 9, 1943

Mr. J. T. Leigh, Water Commissioner Cedar City, Utah

Dear Sir: RE: COAL CREEK DISTRIBUTION

In your letter of February 24, 1943, it is noted in your report on measuring devices that the Cedar City and West Field Canal has no weir. Also you report that the North-west Field Canal has no weir, and in the one instance, you recommend a submerged orifice and for the other canal you recommend that a weir be installed.

Mr. Monson visited you some time ago. He received from you the size and types of weirs on the various canals. At that time it was his understanding that there was a 4-ft. rectangular weir on each of these canals. In checking over your report, it is important that this apparent discrepancy be cleared up.

I would appreciate an explanation whether or not weirs do exist on these two canals.

Yours very truly,

Ed. H. Watson STATE ENGINEER

I.CM/ner

A Brunk 30 M3

MIN / 19